

**TRUCK REMARKETING SERVICES**

**SPECIFICATION SHEET**

888-790-6996

Fleet Name: Sample Report Unit # TRACTOR VIN (last 6): SAMPLE  
 Location: Truck Remarketing Services Contact:  
 Address: Phone: -- Ext

City: Brookfield State: CT Zip: 06804

Year:	2004	Make:	Volvo	Frame:	Steel
Model:	VN64T-670	Interior Type (Name):	Custom		
Full VIN #	TRACTOR-IN-SAMPLE	Interior Level:	Mid		
Engine Make:	Cummins	Model:	ISX 400ST	Interior Upholstery:	Vinyl, Cloth
HP (rated):	400	HP (ECU):	400	Seat Suspension:	Dual Air
Sleeper:	Integral-Raised	Size:	61 "	Fuel Tanks:	Alum
				Tank Capacity:	1: 150 2: 150 3: N/A
Wheel Base:	224 "	Bumper:	Aero		
Odometer:	430,458	ECU:	430,330	Interior Color:	Gray
Hubometer:	N/A	Paint Color:	White		
Transmission Make:	Eaton-Fuller	Exhaust:	Single Vertical		
Model:	FRO16310C	Speeds:	10	Front Wheels:	Alum
Type:	Manual	Radio:	<input checked="" type="checkbox"/> AM/FM <input type="checkbox"/> Cassette		
Suspension:	Air-Ride		<input checked="" type="checkbox"/> CD <input checked="" type="checkbox"/> Weather Band		
Front Axle Make:	Meritor	Capacity:	12,350		<input type="checkbox"/> Satellite <input type="checkbox"/> No Radio
Front Axle Position:	Set-Back	PTO:	No		
Rear Axle Make:	Meritor	Capacity:	38,000	Mirrors:	Heated Dual Power
Type:	Tandem	Ratio:	3.55	Wet Line Kit:	No
3rd Axle:	No	Rear Wheels:	Alum		
		Brakes:	<input checked="" type="checkbox"/> ABS <input checked="" type="checkbox"/> Air		
Power Steering:	Yes		<input type="checkbox"/> Hydraulic <input checked="" type="checkbox"/> Drum <input type="checkbox"/> Disc		
Engine Brake:	Jake	New Paint:	Yes		
		Dual Beds:	Yes		
Air Conditioning:	Yes	Steer Axle Brakes:	80 % 80 %		
Fuel Type:	Diesel	Drive Axle Brakes:	80 % 80 %		
Chassis Fairings:	Partial		80 % 80 %		
Roof Fairing:	No	3rd Axle Brakes (if applicable):	% %		
		Brake Backing Plates (Dust Shields):	Front: No		
Side Extenders:	Yes		Rear: Yes		
Cab Type:	Conventional	Engine Serial #	79031-Sample		
Body Type:	Tractor	Engine CPL / Arrange. #	8520		
Exterior Visor:	Fiberglass	Engine Hours:	13,717		
5th Wheel:	Air	Wheel Mounting:	Hub-Pilot		

SAMPLE

Tire Size Front:	275/80R22.5			
Rear:	275/80R22.5			
	<b>H</b>	<b>W</b>	<b>H</b>	<b>H</b>
		4 /32		13 /32
	<b>LR X</b>	<b>LR X</b>	<b>LR X</b>	<b>LR X</b>
	8 /32	8 /32	8 /32	8 /32
	<b>LR X</b>	<b>LR X</b>	<b>LR X</b>	<b>LR X</b>
	5 /32	7 /32	7 /32	7 /32
	/32	/32	/32	/32

Brake Legend			
BD = Bad Drum	CL = Cracked or Separated Lining	LS = Leaking Seal	
Tire Legend			
C = Cut	D = Dry Rot	F = Flat	M = Mismatched Tread or Casings
MA = Mismatched Axles (front vs. rear)			
R = Recap	V = Virgin	W = Irregular Wear	X = Capped More Than Once
Tread Legend			
H = Highway L = Lug			

				CONDITION REPORT	VIN # (last 6 or 8)	SAMPLE	
X \	FIXED?	ITEM	READING	CODE	PROBLEM	PIC #	EST
<b>ENGINE COMPARTMENT</b>							
\		Engine oil - Condition & Level					
X		Coolant - Level & Condition			Coolant level low		200
X		Record coolant protection level (Fahrenheit)	?		Too low to sample		-
\		Radiator, reservoir, hoses					
\		Fan hub / clutch, blade, shroud					
\		Air intake - manifold, air-to-air & piping					
\		Belt alignment, condition & adjustment					
\		A/C compressor, clutch & brackets					
\		Engine oil & fuel leaks			Engine has been steam cleaned		
\		Steering gear, draglink, pump & hoses					
\		Air compressor, governor & hoses					
\		Exhaust system - manifold, turbo & piping			Turbo is new		
\		Starter & solenoid					
X		Charging system - Record voltage	12.8		Too low		200
<b>INSIDE CAB AND SLEEPER</b>						PIC #	EST
\		Start engine - Listen for unusual noises					
X		Clutch & clutch brake adjustment			Clutch brake inop		200
\		Steering wheel, tilt column, shafts & u-joints					
\		Glass - windshields, doors & mirrors					
X		Windshield wipers & washers			Left washer hose broken		50
\		Mirrors - heat & power operation & condition					
\		Door hinges, latches, regulators & knobs					
X		Seats - air operation & condition			Driver armrest missing		75
\		Seat belts & bunk restraints					
X		Upholstery, carpet, mats, etc....			Carpet stain, interior dirty		200
\		Sleeper / cab privacy curtains & tracks					
\		Cabinets, doors & hinges					
X		Dash, gauges, switches & interior lights			ABS ECU has codes recorded (estimate is for siagnose only), Right door light lens missing		150
\		Engine monitor display & LCD readout					
N		Engine brake			Did not activate; vehicle was parked		
\		Radio & speakers					
\		Horns - city & air					
\		Parking brake					
\		Air pressure build up - Governed psi	120				
\		Air leaks - dash, foot valve, shift knob, etc...					
\		HVAC system, fans, control panels & vents					

